

# JUSTIA

## BEAVER COACH PATRIOT 2008: STEERING:GEAR BOX:SHAFT SECTOR

**Make :** BEAVER COACH      **Model :** PATRIOT      **Year :** 2008

**Build Dates :** 2007-08-27 - 2007-11-14

**NHTSA CAMPAIGN ID Number :** 07V590000

<b>Date Owner's Notified:</b>	<b>Date Received by ODI:</b>	<b>Date Added to Database:</b>
2008-01-25	2007-12-20	2007-12-20

**Manufacturers Involved:** MONACO COACH CORPORATION

**Manufacturer's Responsible for the Recall:**

**Manufacturer Campaign Number:** R07042

**Component:** STEERING:GEAR BOX:SHAFT SECTOR

**Potential Number Of Units Affected :** 96

### **Summary:**

ON CERTAIN CLASS A MOTOR HOMES EQUIPPED WITH TRW STEERING GEARS, MODELS TAS85 AND RCS85, THESE STEERING GEARS CONTAIN POTENTIALLY DEFECTIVE SECTOR SHAFTS WITH AN INCORRECT GEAR TOOTH WHICH MAY INTERFERE WITH THE RACK-PISTON TEETH, RESULTING IN A STICK OR BIND CONDITION.

### **Consequence:**

THIS CONDITION HAS THE POTENTIAL TO CAUSE THE STEERING GEAR TO STALL AND RESTRICT THE STEERING TURNING ANGLE OF THE VEHICLE WHICH COULD RESULT IN A VEHICLE CRASH.

### **Remedy:**

MONACO IS WORKING WITH TRW TO REPLACE THE DEFECTIVE STEERING GEAR "PLEASE SEE 07E101". THE RECALL BEGAN ON JANUARY 24, 2008. OWNERS MAY CONTACT MONACO AT 1-800-685-6545 OR TRW AT 1-765-429-1768.

**Report Initiator:** MFR

**V Report**

**Regulation Part  
Number:**

**Federal Motor Vehicle Safety Standard Number:**

**Notes:**

MONACO RECALL NO. R07042. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 'TTY 1-800-424-9153', OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).