

BEAVER COACH PATRIOT THUNDER 2005: EQUIPMENT:RECREATIONAL VEHICLE:LPG WATER HEATER

Make : BEAVER COACH **Model :** PATRIOT THUNDER **Year :** 2005

Build Dates : 2002-12-01 - 2005-04-01

NHTSA CAMPAIGN ID Number : 05V223000

Date Owner's Notified: 2005-05-12 **Date Received by ODI:** 2005-05-13 **Date Added to Database:** 2005-05-13

Manufacturers Involved: MONACO COACH CORPORATION

Manufacturer's Responsible for the Recall:

Manufacturer Campaign Number:

Component: EQUIPMENT:RECREATIONAL VEHICLE:LPG WATER HEATER

Potential Number Of Units Affected : 1606

Summary:

ON CERTAIN CLASS A MOTOR HOMES EQUIPPED WITH VEHICLE SYSTEMS' AQUA-HOT AND HYDRO-HOT WATER HEATERS, WHICH USE WEBASTO BURNER TUBES, THE BURNER TUBES DO NOT MEET SPECIFICATIONS AND COULD FAIL PREMATURELY.

Consequence:

THE SURFACE TEMPERATURE OF THE EXHAUST TUBE EXITING FROM THE HEATER CAN INCREASE AND COULD POTENTIALLY IGNITE COMBUSTIBLE MATERIALS IN OR AROUND THE VEHICLE.

Remedy:

DEALERS WILL REPLACE THE COMBUSTION CHAMBERS "BURNER TUBES" WITH A NEW ONE FREE OF CHARGE. OWNERS MAY CONTACT MONACO AT 1-800-685-6545.

Report Initiator: ODI

V Report

**Regulation Part
Number:**

Federal Motor Vehicle Safety Standard Number:

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 'TTY 1-800-424-9153', OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).