

Control # 006020200312
 Date Taken 03/05/2020
 Service Meter Reading 51000
 Fluid Run Time 10000
 Fluid Added Gal / Qts 0 / 0
 Fluid Status Changed
 Filter Changed Yes
 Anti-Freeze Negative
 Fuel Negative
 Water Negative
 Visc 100C 12.8
 Soot 0
 Iron (FE) 26
 Chromium (CR) 1
 Lead (PB) 0
 Copper (CU) 0
 Tin (SN) 0
 Aluminum (AL) 1
 Nickel (NI) 0
 Silver (AG) 0
 Silicon (SI) 5
 Potassium (K) 2
 Sodium (NA) 5
 Boron (B) 212
 Magnesium (MG) 539
 Calcium (CA) 1629
 Barium (BA) 0
 Phosphorus (P) 815
 Zinc (ZN) 945
 Molybdenum (MO) 104
 Titanium (TI) 0
 Vanadium (V) 3
 Fuel % 0



Lab One Inc.

Oil Analysis since 1985

Mail to: PO Box 20210 - Phoenix, AZ 85036-0210
 Ship to: 101 W Mohave St. - Phoenix AZ 85003

Phone
 Local: 480-839-5221
 Toll Free: 866-652-2663
 Fax: 480-839-9987

Normal

1 of 1

03/12/2020

Make / Model

BEAVER MONACO CAT C-9

Unit/Serial

MOTORHOME/

Compartment

Diesel Engine

Fluid Type

SHELL ROTELLA 15W40

WO / Reference

Current Interpretation

No abnormal wear or contaminants detected.

0000008746

Andrew Shoen
 Attn:
 30 Berkeley Ave
 San Anselmo

Registered By
 CHRISTINE SMITH

Interpreted By
 JASON KRONLUND

This analysis is intended as an aid in predicting mechanical wear. No guarantee, expressed or implied, is made against failure of this component.